

Field Investigation: Erosion and Sedimentation Controls

Date:	October 3, 2025	CC:	
Investigator:	Aleksandra Moch	Address:	45 Cedar Hills
Project Activities	Fill removal and wetland buffer restoration	Owner: Contact info:	Jonathon and Diane Gelbwaks

Control Measure	Inspection Notes
Silt Fence:	Two rows of silt fence with a line of hay bales in between were installed along the toe of the fill to protect the wetland/watercourse area behind.
Construction Fence:	No construction fence is required. The silt fence acts as a construction one.
Anti-tracking pad:	No anti-tracking pad, the access will be via the existing driveway.
Other:	I met with the contractor and the owners. We walked the site, and I provided a copy of the approved site plan and the planning plan for their reference.
Notes:	The site is ready for the activities.
Follow-up required:	Yes, after the fill is removed but before the planting activities.



Double line of silt fence with hay bales in between. View from the west of the northern and middle section.

A. Moch 10/3/2025



Double line of silt fence with hay bales in between. View from the west of the southern stretch. A. Moch 10/3/2025